

TURBO COMPONENTS

****GERMAN MALIBU CLUB SPECIAL - 10% OFF FROM 07/16/05 THRU 07/31/05**

ON HAND



NEW VALVE HOUSING. INCLUDED!!

Wastegate

Includes all of the following series: 470908,481064, 470818,470954,470842,481036. Overhaul with new Gate assemblies. Units with serviceable gate offered at lower prices when available.
Price: \$690.00

Type: Exchange/Overhaul
 Core Charge: \$400.00

Pressure Relief Valves

470930 Series, 470944 Series & 481028 Series. Most units in stock for exchange. We can overhaul your unit same day if needed.

Price: \$290.00
 Type: Exchange/Overhaul
 Core Charge: \$400.00

Turbochargers

Full line of Turbochargers. Overhauls, factory new, and factory overhaul units available. Please call for prices, availability and core charges.

Price: Call
 Order #: Consult OEM manual
 Type: Exchange, Overhaul & Factory New
 Core Charge: Call

Oil Seal Assembly

Repair per FAA Repair Specification on oil seal for the Rajay Turbochargers.

Price: 230.00
 Order #: 600369
 Type: Repair—Exchange only.
 Core Charge: \$100.00

Wastegate Valve Assemblies

PMA approved assemblies to replace 4772400003, 4772400004 & 4781600001. Housings, shafts, bushings and butterflies also sold separately.
Price: \$399.00 (Assembly Price)

Type: New Parts
 Housing: \$265.00 Shaft: \$40.00
 Bushings: \$35.00 Butterfly: \$75.00
*******KITS*******
 1 Shaft+2 Bushings+1Butterfly+ 1 Groove Pin,
 2 Retainer Rings for \$190.00 ea.(Qty 1 - 15)
 Qty of 16 + for \$180.00 ea.

Boot Bellows

Repair to part Numbers 476226 -0001, 0002, and 0003 per FAA Approved Process Spec
 Price \$120.00 (476-0002 &-0003 each
 Price \$175.00 (476226-0001 & -0004 each
 Type Repair
 Core Charge \$100.00



ON HAND

Controllers

All Series. Exchange units available or same day turn of your unit.

Price: \$690.00 (All Series Except Dual Controllers)
 Price: \$1,190.00 (470782, 470948 & 470934)
 Order #: Consult OEM manual for part no.
 Type: Exchange/Overhaul
 Core Charge: \$400.00 All series except Dual Controllers
 Core Charge: \$550.00 (470782,470948 & 470934)

We also carry:

U-CUP

FAA approved PMA replacement part for OEM part no. 476884-0002 Priced at \$55.00 Each
 Order # PM476884-2

Rear Bearing Kit

FAA approved PMA replacement part for OEM part no.# 90-2014—Priced at \$37.00each (Qtys 1-9) , \$34.00 Each (Qtys 10 +). Order # PM90-2014



New items just added in 3/2005

THO Series PMA WHEEL SHROUD
 REF. PART NUMBER 407657-0002

TEO Series PMA WHEEL SHROUD
 REF. PART NUMBER 407778-0002

ON HAND



ON HAND



ON HAND



ON HAND

